





CRANE INCIDENT


The following pictures are of a crane incident that occurred in the Netherlands at Shell's Antwerp Refinery. During a major turnaround, fan tubes were being lifted using a tube tray. During the lift and while the tube tray was directly over the crane operator's cab, the tube tray deviated from horizontal, and the fan tubes slid off and plunged like arrows into the operator's cab. Note that the tubes were not properly secured to the tray during the lift operation. The attached pictures show the condition of the operator's seat just after the accident. Amazingly (and thankfully), the operator suffered only minor scratches in one leg.


The pictures tell the tale.



















CRANE INCIDENT

This is a reminder to take all "lifts" seriously, from the lightest and least complex to the heaviest and most complex. Proper rigging and securing of loads SAVES LIVES.